



● Semi -auto blowing machine+heat oven

1. blowing machine (1 cavity or 2 cavities)



2. heat oven





3. moulds



4. air compressor-high pressure (to produce the high pressure air to blow the perform in the mould)



5. Compressor groupware (to deal the pressured air clean, dry etc, it is necessary for guarantee the blow quality)



6. air compressor-low pressure

(to produce the lower pressure air to run the relevant parts in the blowing machine, for its operation)

